RIPJAWS KM780 MX Changelog

Software Version: 0.91
Firmware Version: 29

Notes:

- Fixed a bug where recording macros in AZERTY keyboard layout would output as QWERTY keys.