RIPJAWS MX780 Changelog

Software Version: 0.78
Firmware Version: 21

Notes:

- Fixed a bug where the software UI language does not match the system language upon install.
- Fixed a bug where the software does not correctly read the saved DPI values on the mouse.
- Fixed a bug where macro would not work after restarting the Windows OS.
- Fixed a bug where the “Sniper” function would be stuck to 100 dpi.
- Fixed a bug where the “Breathing” lighting effect would not display in sync.
- Fixed some language errors in the UI.
- Various bug fixes